

Outer Shell Fabric and Finish	Condition	Direction	Indices of Penetration, Repellency, Absorption			Flame Resistance	
			I_P	I_R	I_A	Average Afterflame (s)	Average Char Length (mm)
PBI MAX 6.0	Fuel Contamination	Warp	30.0	3.4	64.6	17.9	9
		Fill	31.7	1.4	66.0	17.6	11
	Fuel Contamination followed by Cleaning	Warp	27.7	0.8	67.9	0.0	16
		Fill	27.7	2.1	64.8	0.9	17
	As Received	Warp	N/A	N/A	N/A	0.0	18
		Fill	N/A	N/A	N/A	0.0	15
	After 5 Launderings	Warp	N/A	N/A	N/A	0.0	14
		Fill	N/A	N/A	N/A	0.0	17